

D&D Facility Characterization Interview Checklist

ID No.: 770

Date: 10/09/00

Page 1 of 2

Check	List	for -	Title	ח&ח	Facility	Characterization -	Interviews
CHOCK	LIGI	101 -	HILIO.		1 acmev	Characterization -	HILLEI AIG MA

CRITERIA:

A D&D Characterization Protocol, RFETS MAN-077-DDCP, Rev. 0

A Facility Disposition Program Manual, RFETS MAN-076-FDPM

Λ RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) Building 770, Type 2 Facility, Offices and Stockroom Facility							
Personnel Interviewed (Name & Title/Function) Don L. Cox, Mechanical Engineer V, D&D Closure							
Y/N							
Does a current WSRIC exist for the facility?							
If so, are there exceptions to the WSRIC as written?							
COMMENTS (incl. WSRIC contacts)							
WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83. Are rad surveys available that indicate current status of the facility?							
Are rad surveys available that indicate current status of the facility?							
Are historical rad surveys available that indicate historical status, or evolution, of the facility? Y							
COMMENTS N* According to Sarah J. Roberts, X3008, ARCDA, T771Q, any historical data, which is							
probably at the Federal Center, would not be adequate for unrestricted release (i.e. Pre-Demolition Survey							
or Property release Evaluation). New monitor surveys would have to be taken.							
Is an HRR available for the facility? Y							
Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further							
Characterize the facility relative to chemical &/or radiological contamination?							
Are engineering drawings (esp. "as-builts") available?							
Are any nonconformances or issues with the facility status currently being tracked in PATS? N							
If so, what are the issues (note in Comments, below)?							
COMMENTS The building sits on UBC 770 & IHSS 150.1 area land/soils. The Plant quit using lead based							
paint in the 1980's, if this facility was painted prior to this time lead based paints may have been used.							
Have any types of chemical characterization, incl. asbestos, been performed recently?							
If so, what types of characterization were performed (note in Comments, below)?							
COMMENTS N* No asbestos characterization data exists for Building 770, Offices and Stockroom							
Facility, according to Bret Clausen X7781, Building 130, Room C-252. The asbestos data reports are							
located in Cubicle 273 of building 130 and the reports are under the control of Bret Clausen with Rae							
Eklund as backup contact for the asbestos reports.							
Interviewed by: D. A. Burton / Subsufm / 10/09/00							
Print Name Signature Interview Date							



ADMIN RECCRD

IA-A-000661



Print Name

D&D Facility Characterization Interview Checklist

ID No.: <u>770</u>

Date: 10/09/00

Page 2 of 2

What timeframe did the interviewee work in the facility? 1974 to 2000
Has the building configuration changed since you worked in the building? If so, in what way? Yes. The building was originally was constructed as a pipe shop for construction workers. It was then converted to a waste drum and box storage facility. Then it was converted into its present use as offices and a stockroom.
What types of equipment were in the building during the interviewee's time there? Various types of equipment used in the fabrication of pipe for installation in Building 771 and equipment for handling waste drums and boxes.
Where was the equipment located? (specific rooms/areas) In the building.
Were any radioactive materials or metals handled in the building? If so, what types? Yes. Waste drums and boxes
Which equipment handled radioactive material? <u>Drum dollies and forklift trucks.</u>
Were any chemicals handled in the building? If so, what types? Yes. Pipe cutting fluids and cleaning solutions.
Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? Yes
Were these spills/releases cleaned-up? Yes
Where did these spills/releases occur? Inside and outside the building.
Interviewed by: D. A. Burton / Nassunfan / 10/09/00

Signature

Interview Date

2/2